

ARTISAN®
TECHNOLOGY GROUP

Your **definitive** source for quality pre-owned equipment.

Artisan Technology Group
(217) 352-9330 | sales@artisantg.com | artisantg.com

Full-service, independent repair center
with experienced engineers and technicians on staff.

We buy your excess, underutilized, and idle equipment
along with credit for buybacks and trade-ins.

Custom engineering
so your equipment works exactly as you specify.

- Critical and expedited services
- In stock / Ready-to-ship
- Leasing / Rentals / Demos
- ITAR-certified secure asset solutions


Expert team | Trust guarantee | 100% satisfaction

All trademarks, brand names, and brands appearing herein are the property of their respective owners.

Find the *OMRON / Adept Technology AWCII* at our website: *Click HERE*

AdeptWindows Controller (AWC-II) Board Connectors and Indicators

An AWC-II system processor board is required for all Adept controllers and can be configured with a 68040 or 68060 CPU. This section describes the basic features of the AWC-II board.



1. Status LEDs.
   Six two-color LEDs indicate diagnostic test, power control, and communication status.

   SF/OK: red LED = System Fault, green LED = System OK
   ES/HPE: red LED = E-Stop open, green LED = High Power Enabled
   HD/LAN: red LED = Read / Write from CF, green LED = Ethernet access

   During system bootup the red SF/OK and ES/HPE LEDs are lit and the red HD/LAN LED blinks. After system bootup, the SF/OK LED should show green. If the ES/HPE LED shows red, the E-Stop circuit is open. During compact flash reads and writes, the HD/LAN LED pulses red. When the AWC-II is active on an Ethernet network, the HD/LAN LED pulses green.

2. Two RS232 ports and one RS422/485 port. (Refer to the *Adept MV Controller User's Guide* for pin descriptions and locations.)

3. Ethernet connector: Shielded RJ-45 receptacle that supports 10 BaseT communications. (Refer to the *Adept MV Controller User's Guide*.)

4. Controller Interface Panel (CIP2): connector that accepts a standard 50-pin SCSI cable that routes signals and information to the CIP2. Note that the CIP2 does not communicate in SCSI format. (See **Section 3.3 on page 34** through **Section 3.6 on page 35** for basic installation details and refer to the *Adept MV Controller User's Guide* for complete details.)

5. Three IEEE 1394 ports: Top port connects to the Multi-Access Interface (MAI) module in the PA-4 chassis.

Figure 3-3. AWC-II Controller Board

Artisan Technology Group - Quality Instrumentation ... Guaranteed | (888) 88-SOURCE | www.artisantg.com

Artisan Technology Group is an independent supplier of quality pre-owned equipment

Gold-standard solutions

Extend the life of your critical industrial, commercial, and military systems with our superior service and support.

We buy equipment

Planning to upgrade your current equipment? Have surplus equipment taking up shelf space? We'll give it a new home.

Learn more!

Visit us at **artisantg.com** for more info on price quotes, drivers, technical specifications, manuals, and documentation.

Artisan Scientific Corporation dba Artisan Technology Group is not an affiliate, representative, or authorized distributor for any manufacturer listed herein.

We're here to make your life easier. How can we help you today?

(217) 352-9330 | sales@artisantg.com | artisantg.com

ARTISAN® TECHNOLOGY GROUP