

ARTISAN®
TECHNOLOGY GROUP

Your **definitive** source for quality pre-owned equipment.

Artisan Technology Group
(217) 352-9330 | sales@artisantg.com | artisantg.com

Full-service, independent repair center
with experienced engineers and technicians on staff.

We buy your excess, underutilized, and idle equipment
along with credit for buybacks and trade-ins.

Custom engineering
so your equipment works exactly as you specify.

- Critical and expedited services
- In stock / Ready-to-ship
- Leasing / Rentals / Demos
- ITAR-certified secure asset solutions

Expert team | Trust guarantee | 100% satisfaction

All trademarks, brand names, and brands appearing herein are the property of their respective owners.

Find the *VIAVI Solutions / JDSU / WWG ANT-20SE* at our website: *Click HERE*

```
Customer:unknown
SYSTEM CONFIGURATION

Customer Infos
  Customer

  Comment

  Date - Time
    Mon Mar 22 10:42:52 2004

Device Infos
  Reference status
    Item No. of Master Version: 3035-9386.021
    Date: 04/23/2001
  Device
    Device number :     FH-209
General
  Software Version
    User Interface :     8.00
    Base Module :        8.00
  Version
    Instrument Version :         ANT-20 3035/22
    Edition :   3060/02  ANT-20SE SONET
  SKA
    Id :                 0020
    Ini :        C:\ANT20\ANT20_ED\20.INI
    Text :       3060/02  ANT-20SE SONET
    BUP :        C:\ANT20\ANT20_ED\ANT_20SE.BUP
  Existing Options
    3035/90.01   Mapping C12
    3035/90.02   34 Mbps in C3 Mapping
    3035/90.03   Mapping C4
    3035/90.04   Mapping C11
    3035/90.05   45 Mbps in C3 Mapping
    3035/90.06   Mapping C2
    3035/90.10   Mapping VT1.5 SPE
    3035/90.11   Mapping VT6 SPE
    3035/90.12   DS3 in STS-1 SPE Mapping
    3035/90.13   E1 in VT2 SPE Mapping
    3035/90.15   Extended Overhead Analysis
    3035/90.33   Bit Error Test 2/8/34/140 Mbps
    3035/90.34   Bit Error Test 1,5/45 Mbps
    3035/90.48   Optics STM-1/4, OC-1/3/12, 1310&1550
    3035/90.90   OC-12c/STM-4c BERT
    3035/90.93   OC-48c/STM-4c BERT
    3035/91.59   New STM-16 1310 / 1550
    3035/92.10   GPIB Remote Control
Base Module
    Series :     FH-209
    Dongle :     011C74A20700
    Edition :    0C01/0260
Interface
    Edition :    0C01/0163
Flex Mux
    Edition :    0C01/0656
Optics STM-1/4
    Edition :    0C01/0461
Optics STM-16
    Edition :    0C01/1359
    Dongle  :    01FD7AA20700
    Serial No. :         AF-005
Optics STM-64 TX
    not installed
```

```
Optics STM-64 RX
    not installed
Miniflex
    Edition :    0C01/1153
Jittermodule for DS-1 to STM-4/OC-12
    not installed
Jittermodule for STM-16/OC-48
    not installed
BAG Module (ATM SVC Tester)
    not installed
Operating Computer
  CPU
    Intel Pentium Pro
  CMOS-Ram
    Byte 00 - 0F :   53  46  42  23  10  10  00  22  03  04  26  02  50  80  00  00
    Byte 10 - 1F :   00  00  30  00  00  80  02  00  FC  01  01  00  01  01  00  01
    Byte 20 - 2F :   01  00  01  01  00  30  80  00  00  00  00  00  00  0E  02  74
    Byte 30 - 3F :   00  FC  20  42  E0  7C  13  00  00  00  00  0A  80  5F  59  15
    Byte 40 - 4F :   02  01  10  4B  11  03  22  22  FF  FF  FF  FF  FF  FF  FF  FF
    Byte 50 - 5F :   FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF
    Byte 60 - 6F :   FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF
    Byte 70 - 7F :   FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  FF  26
  Memory
    64 MByte
  Video mode
    80 x 25 color
  Video Configuration
    X pixels :  640
    Y pixels :  480
    Color bits / pixel :        24
  Number of floppy-disk drives
    1 installed
  Direct Memory Access (DMA) chip
    installed
  Number of RS232 serial ports
    2 installed
  Number of parallel ports
    3 installed
  Operating System
    DOS version :       7.10
    Windows version :   3.95 (863)
Registry
  Windows Version
    Windows  98 IE 5 5.00.2614.3500   A
Configuration (pf90uif.ini)
  [ConfigDirectories]
    virtinst=cfg\virtinst
    mbsi=cfg\mbsi
  [MBSIs]
    mbsi=atmmbsi.ini
    mbsi=jitmbsi.ini
    mbsi=j16mbsi.ini
    mbsi=basembsi.ini
    mbsi=j64mbsi.ini
  [Instruments]
    vi=frameed.ini
    vi=dains.ini
    vi=meas.ini
    vi=pan.ini
    vi=pdh.ini
    vi=sohtx.ini
    vi=sohrx.ini
    vi=ptrgen.ini
    vi=ptranal.ini
    vi=jit.ini
```

```
    vi=jit_o172.ini
    vi=ass.ini
    vi=ata.ini
    vi=abg.ini
    vi=acc.ini
    vi=acr.ini
    vi=acs.ini
  [Settings]
    Operation Mode=0
    MainWndPos=0,1,171,408,59,125,0,0,640,72
    StoreMode=STORE_OFF
    MiniBarPos=40,1
    ResultWarning=1
    KeyboardLocked=0
    AmCompact=0
  [ErrorWnd]
    ShowOnError=ON
    TopOnError=ON
  [Recent File List]
    File1=C:\ANT20\MEASAPP\AT_START.APL
    File2=C:\ANT20\APPLS\NEW_02.APL
  [MISC]
    STM16-ID="0C01/1359"
    OVERHEAD=16
    TXOVERHEAD=16
    STM64-RX-ID=""
    STM64-TX-ID=""
System Memory
    Free memory space :  66457600
    Free user resources :        97%
    Free gdi resources :         97%
Working directory
    working directory :  C:\ANT20\APPLS
Files
  EXE:
    ANTSTART.EXE
    WGWSSERV.EXE         Vers. 8.00
    STM64SPY.EXE         Vers. 8.00
    J16MBSI.EXE  Vers. 8.00
    J64MBSI.EXE  Vers. 8.00
    PDH.EXE      Vers. 8.00
    GSW.EXE      Vers. 2.5.1.0
    ATMMBSI.EXE  Vers. 8.00
    ASS.EXE      Vers. 8.00
    ABG.EXE      Vers. 8.00
    PTRGEN.EXE   Vers. 8.00
    SOHTX.EXE    Vers. 8.00
    BASEMBSI.EXE         Vers. 8.00
    SOHRX.EXE    Vers. 8.00
    PTR_ANAL.EXE         Vers. 8.00
    PAN.EXE      Vers. 8.00
    ACS.EXE      Vers. 8.00
    PF90UIF.EXE  Vers. 8.00
    DAINS.EXE    Vers. 8.00
    ATA.EXE      Vers. 8.00
    ACR.EXE      Vers. 8.00
    MEAS.EXE     Vers. 8.00
    ACC.EXE      Vers. 8.00
    FRAMEED.EXE  Vers. 8.00
    JITMBSI.EXE  Vers. 8.00
    JIT.EXE      Vers. 8.00
    JIT_O172.EXE         Vers. 8.00
  DLL:
    AMHOOK.DLL
    ANTTIMER.DLL
```

```
    VEPPAPI.DLL
    PARS_DLL.DLL
    DIBAPI.DLL
    GSWDLL.DLL   Vers. 2.5.1.0
    COMMOD.DLL
    ASCIKEYB.DLL
    WGWSDRVW.DLL
    ANTKEYB.DLL
    SYSOBJCT.DLL
    WGWSCOMM.DLL
    ANT_DLGS.DLL         Vers. 8.00
    BWCC.DLL
    DBS_DLL.DLL
    APM_SERV.DLL
    MBSIARCH.DLL
    MFCOLEUI.DLL         Vers. 2.00
    APPL_DLL.DLL
    PF90ARCH.DLL
    ATMMOD.DLL
    CB5.DLL
    BASEMOD.DLL
    JITTER.DLL
Running Applications
    WG Antinfo
    WG Device Info - FH-209
    DDE Server Window
    The Hello Program
    Power Meter
    DDE Server Window
    OleMainThreadWndName
    Multimedia Input Service
    Hello World!
    MS_WebcheckMonitor
    Program Manager
Measurement Computer
Configuration (C:\ANT20\mb\ant20cnf.ini)
  [System]
    BIOSVersion=15
    EPLDVersion=33
    RAMSize=40
  [Modules]
    Module0=0,0 ; 000,00
    Module1=0,0 ; 000,00
    Module2=3073,19     ; C01,13
    Module3=3073,1      ; C01,01
    Module4=3073,2      ; C01,02
    Module5=0,0 ; 000,00
я
```

Artisan Technology Group is an independent supplier of quality pre-owned equipment

Gold-standard solutions

Extend the life of your critical industrial, commercial, and military systems with our superior service and support.

We buy equipment

Planning to upgrade your current equipment? Have surplus equipment taking up shelf space? We'll give it a new home.

Learn more!

Visit us at **artisantg.com** for more info on price quotes, drivers, technical specifications, manuals, and documentation.

Artisan Scientific Corporation dba Artisan Technology Group is not an affiliate, representative, or authorized distributor for any manufacturer listed herein.

We're here to make your life easier. How can we help you today?

(217) 352-9330 | sales@artisantg.com | artisantg.com

ARTISAN® TECHNOLOGY GROUP