



Artisan Technology Group is your source for quality new and certified-used/pre-owned equipment

- FAST SHIPPING AND DELIVERY
- TENS OF THOUSANDS OF IN-STOCK ITEMS
- EQUIPMENT DEMOS
- HUNDREDS OF MANUFACTURERS SUPPORTED
- LEASING/MONTHLY RENTALS
- ITAR CERTIFIED SECURE ASSET SOLUTIONS

SERVICE CENTER REPAIRS

Experienced engineers and technicians on staff at our full-service, in-house repair center

*InstraView*SM REMOTE INSPECTION

Remotely inspect equipment before purchasing with our interactive website at www.instraview.com ↗

WE BUY USED EQUIPMENT

Sell your excess, underutilized, and idle used equipment. We also offer credit for buy-backs and trade-ins. www.artisanng.com/WeBuyEquipment ↗

LOOKING FOR MORE INFORMATION?

Visit us on the web at www.artisanng.com ↗ for more information on price quotations, drivers, technical specifications, manuals, and documentation

Contact us: (888) 88-SOURCE | sales@artisanng.com | www.artisanng.com

Part Number Listing



Effective Date: December 1, 2003



4126 Linden Avenue
Dayton, OH 45432-3068 USA
Phone: 937-252-5601
Fax: 937-258-2729

Product specifications subject to change without notice.

Systran is a trademark of SYSTRAN Corporation
1553 Solutions is a trademark of SYSTRAN Corporation
BusXchange is a trademark of Systran Corporation
DEC, AXP, Open VMS and VMS are registered trademarks of Digital Equipment Corp.
Q-bus is a trademark of Digital Equipment Corporation.
LabVIEW is a trademark of National Instruments Corporation.
Motorola and Power PC are registered trademarks of Motorola Corp.
VxWorks is a registered trademark of Wind River Systems Corp.
MS-DOS, Windows and Windows NT are registered trademarks of Microsoft Corp.
Pentium is a registered trademark of INTEL Corp.
UNIX is a registered trademark of the Open Group
Resource Allocation Manager is a trademark of SAIC
CompactPCI is a registered trademark of PCI Industrial Computers Manufacturers Group
All other trademarks or registered trademarks mentioned herein are the sole property of their respective owners.

© 2003 SYSTRAN Corp. All Rights Reserved.

PC-AT BUS (Including Software)

- PC-AT GoldPlus Single mode at a time 1
- PC-AT GoldPlus Multiple modes at a time 2

PCI (Including Software)

- PCI GoldPlus Single mode at a time 3
- PCI GoldPlus Multiple modes at a time 3

CompactPCI (Including Software)

- CompactPCI GoldPlus Single mode at a time 4
- CompactPCI GoldPlus Multiple modes at a time 4

PMC (Including Software)

- PMC GoldPlus Single mode at a time 5
- PMC GoldPlus Multiple mode at a time 5

VME BUS (Including Software)

- BIU Express VME Single mode at a time 6
- VME GoldPlus Single mode at a time 7
- VME GoldPlus Multiple modes at a time 8

VXI BUS (Including Software)

- VXI (Register-Based) GoldPlus Single mode at a time, "C" size 9
- VXI (Register-Based) GoldPlus Multiple modes at a time, "C" size 10

SWITCHES

- BusXchange Multiplex Bus Switch 11
- Resource Allocation Manager Software for BusXchange 11
- BusXchange Multiplex Bus Switch Accessory 11

MAINTENANCE

- Hardware Repair 12
- Annual Maintenance 12
- Resource Allocation Manager™ (RAM) Software Maintenance 12

TECHNICAL SERVICES

- Technical Services 12

ACCESSORIES 13

SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729

PC-AT GoldPlus

Single mode at a time

ORDER NUMBER	DESCRIPTION
DHAS-GLD+PC/S-1	1553A/B; One redundant bus; BC, MRT, or BM modes
DHAS-GLD+PC/S-2	1553A/B; Two redundant buses; BC, MRT, or BM modes
DHAS-2900-13318	1553A/1B; One redundant bus; BC, MRT, or BM modes: based on DHAS-GLD+PC/S-1

NOTES:

- All library and diagnostics software includes source code. All software is provided on 3.5" disks. Software part numbers listed below for ordering purposes.
- For the DHAS-GLD+PC/S-1, one 8" cable assembly with jacks (P/N DHAS-30893-8) is included with each board.
- For the DHAS-GLD+PC/S-2, one 8" cable assembly with jacks (P/N DHAS-30894-8) is included with each board.
- For optional cable assemblies, see the Accessories page.
- All boards include 32K words memory per channel.

Software for DHAS-GLD+PC/S-X Products (included with order; select 1)

ORDER NUMBER	DESCRIPTION
DKDM-GPDXAFC-EA	DOS library and diagnostics
DKDM-GPWNAFXB-EA	Windows 3.1 DLL and diagnostics
DKDM-GPWNAFWB-EA	Win3.1, LabWindows/CVI DLL and diagnostics
DKDM-GPWNAFVB-EA	Win3.1, LabVIEW4.0 DLL and diagnostics
DKDM-GPWXAFCM-EA	Win95 DLL and diagnostics
DKDM-GPWXAFCM-EA	Win95, LabWindows/CVI DLL and diagnostics
DKDM-GPWXAFCM-EA	Win95, LabVIEW5.0 DLL and diagnostics
DKDM-GPNTAFXM-EA	WinNT DLL and diagnostics
DKDM-GPNTAFWM-EA	WinNT, Lab Windows/CVI DLL and diagnostics
DKDM-GPNTAFVM-EA	WinNT, LabVIEW5.0 DLL and diagnostics
DKDM-GPWXAFCM-EA	SIMMPL for Windows 95™
DKDM-GPNTAFSM-EA	SIMMPL for Windows NT™

Optional GUI Application Software

ORDER NUMBER	DESCRIPTION
DKDM-GEWBAFGX-EA	GoldExpress for Windows 3.1 and 95 (16 bit)
DKDM-GEWBAFHX-EA	GoldExpress for Windows 3.1 and 95 (16 bit) Demo Disk

*One software package is included with order. Additional software packages are available for \$150.
NC=No Charge (included with hardware)

SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729

PC-AT GoldPlus

Multiple modes at a time

ORDER NUMBER	DESCRIPTION
DHAS-GLD+PC-1	1553A/B; One redundant bus; BC/MRT/BM modes
DHAS-GLD+PC-2	1553A/B; Two redundant buses; BC/MRT/BM modes
DHAS-2900-13317	1553A/B; One redundant bus; BC/MRT/BM modes w: based on DHAS-GLD+PC-1

NOTES:

- All library and diagnostics software includes source code. All software is provided on 3.5" disks. Software part numbers listed below for ordering purposes.
- For the DHAS-GLD+PC-1, one 8" cable assembly with jacks (P/N DHAS-30893-8) is included with each board.
- For DHAS-GLD+PC-2, one 8" cable assembly with jacks (P/N DHAS-30894-8) is included with each board.
- For optional cable assemblies, see the Accessories page.
- All boards include 32K words memory per channel.

Software for DHAS-GLD+PC-X Products (included with order; select 1)

ORDER NUMBER	DESCRIPTION
DKDM-GPDXAFC-EA	DOS library and diagnostics
DKDM-GPWNAFXB-EA	Windows 3.1 DLL and diagnostics
DKDM-GPWNAFWB-EA	Win3.1, LabWindows/CVI DLL and diagnostics
DKDM-GPWNAFVB-EA	Win3.1, LabVIEW4.0 DLL and diagnostics
DKDM-GPWXAFCM-EA	Win95 DLL and diagnostics
DKDM-GPWXAFCM-EA	Win95, LabWindows/CVI DLL and diagnostics
DKDM-GPWXAFCM-EA	Win95, LabVIEW5.0 DLL and diagnostics
DKDM-GPNTAFXM-EA	WinNT DLL and diagnostics
DKDM-GPNTAFWM-EA	WinNT, Lab Windows/CVI DLL and diagnostics
DKDM-GPNTAFVM-EA	WinNT, LabVIEW5.0 DLL and diagnostics
DKDM-GPWXAFCM-EA	SIMMPL for Windows 95™
DKDM-GPNTAFSM-EA	SIMMPL for Windows NT™

Optional GUI Application Software

ORDER NUMBER	DESCRIPTION
DKDM-GEWBAGX-EA	GoldExpress for Windows 3.1 and 95 (16 bit)
DKDM-GEWBAGHX-EA	GoldExpress for Windows 3.1 and 95 (16 bit) Demo Disk

*One software package is included with order. Additional software packages are available for \$150.
NC=No Charge (included with hardware)

SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729

PCI GoldPlus

Single mode at a time

ORDER NUMBER	DESCRIPTION
DHAS-GLD+PCI/S-1	1553A/B; One redundant bus; BC, MRT, or BM modes
DHAS-GLD+PCI/S-2	1553A/B; Two redundant buses; BC, MRT, or BM modes

PCI GoldPlus

Multiple Modes at a time

ORDER NUMBER	DESCRIPTION
DHAS-GLD+PCI-1	1553A/B; One redundant bus; BC, MRT, BM modes
DHAS-GLD+PCI-2	1553A/B; Two redundant buses; BC, MRT, BM modes

NOTES:

- All library and diagnostics software includes source code. Software part numbers listed below for ordering purposes.
- For each single bus board, one 1" cable assembly with jacks (P/N DHAS-30893-1) is included. For each double bus board, one 2" cable assembly with jacks (P/N DHAS-WGD+PCI2) is included. One 6" cable assembly with DB9 connector (P/N DHAS-GLD+PMCAD-6) is included for each board.
- For optional cable assemblies, see the Accessories page.
- All boards include 64K words memory per channel.

Software for DHAS-GLD+PCI/S-X (included with order; select 1)

ORDER NUMBER	DESCRIPTION	MEDIA TYPE
DKDM-GPWDDFSM-RA	SIMMPL for Windows with Record and Playback*	CD ROM
DKDM-GPWDDFRM-RA	Windows NT, Lab Windows 4.0.1 DLL and diagnostics*	CD ROM
DKDM-GPWDDFQM-RA	Windows NT, LabVIEW 5.0 DLL and diagnostics*	CD ROM
DKDM-GPLIDFSG-RA	SIMMPL for Red Hat Linux 6.2 - 9.0	CD ROM
DKDM-GPSLDFSS-RA	SIMMPL for Solaris 8, 9	CD ROM

Note: *Software operates on Windows 98SE, ME, NT 4.0, 2000 and XP.

Optional GUI Application Software

ORDER NUMBER	DESCRIPTION	MEDIA TYPE
DKDM-GENTPFGX-EA	GoldExpress32 for Windows NT 4.0	3.5" Disk
DKDM-GENTPFGX-RA	GoldExpress32 for Windows NT 4.0	CD ROM
DKDM-GENTPFHX-EA	GoldExpress32 for Windows NT 4.0 Demo Disk	3.5" Disk
DKDM-GENTPFHX-RA	GoldExpress32 for Windows NT 4.0 Demo Disk	CD ROM

*One software package is included with order. Additional software packages are available for \$150
NC=No Charge (included with hardware)SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729

CompactPCI GoldPlus

Single mode at a time

ORDER NUMBER	DESCRIPTION
DHAS-GLD+CPA/S-1	1553A/B; One redundant bus; BC, MRT, or BM modes

CompactPCI GoldPlus

Multiple Modes at a time

ORDER NUMBER	DESCRIPTION
DHAS-GLD+CPA-1	1553A/B; One redundant bus; BC, MRT, BM modes

NOTES:

1. All library and diagnostics software includes source code. Software part numbers listed below for ordering purposes.
2. One 1" cable assembly with jacks (P/N DHAS-30893-1) and one 6" cable assembly with DB9 connector (P/N DHAS-GLD+PMCAD-6) are included with each board.
3. For optional cable assemblies, see the Accessories page.
4. All boards include 64K words memory per channel.

Software for DHAS-GLD+CPA/S-X (included with order; select 1)

ORDER NUMBER	DESCRIPTION	MEDIA TYPE
DKDM-GPWDDFSM-RA	SIMMPL for Windows with Record and Playback*	CD ROM
DKDM-GPWDDFRM-RA	Windows NT, Lab Windows 4.0.1 DLL and diagnostics*	CD ROM
DKDM-GPWDDFQM-RA	Windows NT, LabVIEW 5.0 DLL and diagnostics*	CD ROM
DKDM-GPLIDFSG-RA	SIMMPL for Red Hat Linux 7.0 -9.0	CD ROM
DKDM-GPSLDFSS-RA	SIMMPL for Solaris 8, 9	CD ROM

Note: *Software operates on Windows 98SE, ME, NT 4.0, 2000 and XP.

Optional GUI Application Software

ORDER NUMBER	DESCRIPTION	MEDIA TYPE
DKDM-GENTPFGX-RA	GoldExpress32 for Windows NT 4.0	CD ROM
DKDM-GENTPFHX-EA	GoldExpress32 for Windows NT 4.0 Demo Disk	3.5" Disk
DKDM-GENTPFHX-RA	GoldExpress32 for Windows NT 4.0 Demo Disk	CD ROM

*One software package is included with order. Additional software packages are available for \$150
NC=No Charge (included with hardware)SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729

PMC GoldPlus

Single Mode at a time

ORDER NUMBER	DESCRIPTION
DHAS-GLD+PMC/S-1	1553A/B; One redundant bus; BC, MRT, or BM modes

PMC GoldPlus

Multiple Modes at a time

ORDER NUMBER	DESCRIPTION
DHAS-GLD+PMC-1	1553A/B; One redundant bus; BC, MRT, BM modes

NOTES:

- All library and diagnostics software includes source code. Software part numbers listed below for ordering purposes.
- For the DHAS-GLD+PMC/S-1, one 1" cable assembly with jacks (P/N DHAS-30893-1) and one 6" cable assembly with DB9 connector (P/N DHAS-GLD+PMCAD-6) are included with each board. For the DHAS-GLD+PMC-1, one 1" cable assembly with jacks (P/N DHAS-30893-1) and one 6" cable assembly with DB9 connector (P/N DHAS-GLD+PMCAD-6) are included with each board.
- For optional cable assemblies, see the Accessories page.
- All boards include 64K words memory per channel.

Software for DHAS-GLD+PMC/S-1 and DHAS-GLD+PMC-1 (included with order; select 1)

ORDER NUMBER	DESCRIPTION	MEDIA TYPE
DKDM-GPVCDPFSG-EA	SIMMPL for VxWorks 5.3.1	3.5" Disk
DKDM-GPNTDFSM-RA	SIMMPL for Windows with Record and Playback*	CD ROM
DKDM-GPNTDFRM-RA	Windows NT, Lab Windows 4.0.1 DLL and diagnostics*	CD ROM
DKDM-GPNTDFQM-RA	Windows NT, LabVIEW 5.0 DLL and diagnostics*	CD ROM
DKDM-GPLIDPFSG-RA	SIMMPL for Red Hat Linux 7.0 - 9.0	CD ROM
DKDM-GPSLDFSS-RA	SIMMPL for Solaris 8, 9	CD ROM

Note: *Software operates on Windows 98SE, ME, NT 4.0, 2000 and XP.

*One software package is included with order. Additional software packages are available for \$150.
NC=No Charge (included with hardware)

SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729

BIU EXPRESS VME

Single mode at a time

ORDER NUMBER	DESCRIPTION
DHAS-DTI-VME/S-1	1553B; One redundant bus; BC, SRT, or BM modes
DHAS-DTI-VME/S-2	1553B; Two redundant buses; BC, SRT or BM modes

NOTES:

1. All library and diagnostics software includes source code. All software provided on 3.5" disk.
Software part numbers listed below for ordering purposes.
2. All boards include 64K words memory.

Software for DHAS-DTI-VME/S-X Products (included with order; select 1)

ORDER NUMBER	DESCRIPTION
DKDM-VME/SMOT-EA	Motorola UNIX System V library and diagnostics

*One software package is included with order. Additional software packages are available for \$150.
NC=No Charge (included with hardware)

SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729

VME GoldPlus

Single mode at a time

ORDER NUMBER	DESCRIPTION
DHAS-GLD+VME/S-1	1553A/B; One redundant bus; BC, MRT or BM modes
DHAS-GLD+VME/S-2	1553A/B; Two redundant buses; BC, MRT or BM modes

NOTES:

- All library and diagnostics software includes source code. Software part numbers listed below for ordering purposes.
- All boards include 64K words memory per channel.

Software for DHAS-GLD+VME/S-X (included with order; select 1)

ORDER NUMBER	DESCRIPTION	MEDIA TYPE
DKDM-GPVCVFXG-EA	VxWorks 5.3.1 Library and diagnostics (Motorola PowerPC)	3.5" disk
DKDM-GPVCVFXG-GA	VxWorks 5.3.1 Library and diagnostics (Motorola PowerPC)	4mm DAT
DKDM-GPVCVFXG-DA	VxWorks 5.3.1 Library and diagnostics (Motorola PowerPC)	QIC low-density
DKDM-GPMXXFXA-EA	Motorola UNIX System V Library and diagnostics	3.5" disk
DKDM-GPMXXFXA-GA	Motorola UNIX System V Library and diagnostics	4mm DAT
DKDM-GPMXXFXA-DA	Motorola UNIX System V Library and diagnostics	QIC low-density
DKDM-GPVCVFSG-EA	SIMMPL for VxWorks 5.3.1 (Motorola PowerPC)	3.5" disk
DKDM-GPVCVFSG-GA	SIMMPL for VxWorks 5.3.1 (Motorola PowerPC)	4mm DAT
DKDM-GPVCVFSG-DA	SIMMPL for VxWorks 5.3.1 (Motorola PowerPC)	QIC low-density

*One software package is included with order. Additional software packages are available for \$150.
NC=No Charge (included with hardware)

SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729

VME GoldPlus

Multiple modes at a time

ORDER NUMBER	DESCRIPTION
DHAS-GLD+VME-1	1553A/B; One redundant bus; BC/MRT/BM modes
DHAS-GLD+VME-2	1553A/B; Two redundant buses; BC/MRT/BM modes

NOTES:

- All library and diagnostics software includes source code. Software part numbers listed below for ordering purposes.
- All boards include 64K words memory per channel.

Software for DHAS-GLD+VME-X (included with order; select 1)

ORDER NUMBER	DESCRIPTION	MEDIA TYPE
DKDM-GPVCVFXG-EA	VxWorks 5.3.1 Library and diagnostics (Motorola PowerPC)	3.5" disk
DKDM-GPVCVFXG-GA	VxWorks 5.3.1 Library and diagnostics (Motorola PowerPC)	4mm DAT
DKDM-GPVCVFXG-DA	VxWorks 5.3.1 Library and diagnostics (Motorola PowerPC)	QIC low-density
DKDM-GPMXXFXA-EA	Motorola UNIX System V Library and diagnostics	3.5 disk
DKDM-GPMXXFXA-GA	Motorola UNIX System V Library and diagnostics	4mm DAT
DKDM-GPMXXFXA-DA	Motorola UNIX System V Library and diagnostics	QIC low-density
DKDM-GPVCVFSG-EA	SIMMPL for VxWorks 5.3.1 (Motorola PowerPC)	3.5 disk
DKDM-GPVCVFSG-GA	SIMMPL for VxWorks 5.3.1 (Motorola PowerPC)	4mm DAT
DKDM-GPVCVFSG-DA	SIMMPL for VxWorks 5.3.1 (Motorola PowerPC)	QIC low-density

*One software package is included with order. Additional software packages are available for \$150.
NC=No Charge (included with hardware)

SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729

VXI (Register Based) GoldPlus

Single mode at a time, "C" size

ORDER NUMBER	DESCRIPTION
DHAS-GLD+VXI/SC1	1553A/B; One redundant bus; BC, MRT, or BM modes
DHAS-GLD+VXI/SC2	1553A/B; Two redundant buses; BC, MRT, or BM modes

NOTES:

- All library and diagnostics software includes source code. Software part numbers listed below for ordering purposes.
- All boards include 64K words memory per channel.

Software for DHAS-GLD+VXI/SCX Products (included with order; select 1)

ORDER NUMBER	DESCRIPTION	MEDIA TYPE
DKDM-GPMXXFXA-EA	Motorola UNIX System V library and diagnostics	3.5" disk
DKDM-GPMXXFXA-GA	Motorola UNIX System V library and diagnostics	4mm DAT
DKDM-GPMXXFXA-DA	Motorola UNIX System V library and diagnostics	QIC low-density
DKDM-GPVCVFXG-EA	VxWorks 5.3.1 library and diagnostics (Motorola PowerPC)	3.5" disk
DKDM-GPVCVFXG-GA	VxWorks 5.3.1 library and diagnostics (Motorola PowerPC)	4mm DAT
DKDM-GPVCVFXG-DA	VxWorks 5.3.1 library and diagnostics (Motorola PowerPC)	QIC low-density
DKDM-GPWNXFXM-EA	Win3.1 DLL and diagnostics	3.5" disk
DKDM-GPWNXFWM-EA	Win3.1, LabWindows/CVI DLL and diagnostics	3.5" disk
DKDM-GPWNXFVM-EA	Win3.1, LabVIEW4.0 DLL and diagnostics	3.5" disk
DKDM-GPWXXFXM-EA	Win95 DLL and diagnostics	3.5" disk
DKDM-GPWXXFWM-EA	Win95, LabWindows/CVI DLL and diagnostics	3.5" disk
DKDM-GPWXXFVM-EA	Win95, LabVIEW4.0 DLL and diagnostics	3.5" disk
DKDM-GPNTXFXM-EA	WinNT DLL and diagnostics	3.5" disk
DKDM-GPNTXFWM-EA	WinNT, Lab Windows/CVI DLL and diagnostics	3.5" disk
DKDM-GPNTXFVM-EA	WinNT, LabVIEW4.0 DLL and diagnostics	3.5" disk

*One software package is included with order. Additional software packages are available for \$150.
NC=No Charge (included with hardware)

SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729

VXI (Register Based) GoldPlus

Multiple modes at a time, "C" size

ORDER NUMBER	DESCRIPTION
DHAS-GLD+VXI/C-1	1553A/B; One redundant bus; BC/MRT/BM modes
DHAS-GLD+VXI/C-2	1553A/B; Two redundant buses; BC/MRT/BM modes

NOTES:

- All library and diagnostics software includes source code. Software part numbers listed below for ordering purposes.
- All boards include 64K words memory per channel.

Software for DHAS-GLD+VXI/C-X Products (included with order; select 1)

ORDER NUMBER	DESCRIPTION	MEDIA TYPE
DKDM-GPMXXFXA-EA	Motorola UNIX System V library and diagnostics	3.5" disk
DKDM-GPMXXFXA-GA	Motorola UNIX System V library and diagnostics	4mm DAT
DKDM-GPMXXFXA-DA	Motorola UNIX System V library and diagnostics	QIC low-density
DKDM-GPVCVFXG-EA	VxWorks 5.3.1 library and diagnostics (Motorola PowerPC)	3.5" disk
DKDM-GPVCVFXG-GA	VxWorks 5.3.1 library and diagnostics (Motorola PowerPC)	4mm DAT
DKDM-GPVCVFXG-DA	VxWorks 5.3.1 library and diagnostics (Motorola PowerPC)	QIC low-density
DKDM-GPWNXFXM-EA	Win3.1 DLL and diagnostics	3.5" disk
DKDM-GPWNXFWM-EA	Win3.1, LabWindows/CVI DLL and diagnostics	3.5" disk
DKDM-GPWNXFVM-EA	Win3.1, LabVIEW4.0 DLL and diagnostics	3.5" disk
DKDM-GPWXXFXM-EA	Win95 DLL and diagnostics	3.5" disk
DKDM-GPWXXFWM-EA	Win95, LabWindows/CVI DLL and diagnostics	3.5" disk
DKDM-GPWXXFVM-EA	Win95, LabVIEW4.0 DLL and diagnostics	3.5" disk
DKDM-GPNTXFXM-EA	WinNT DLL and diagnostics	3.5" disk
DKDM-GPNTXFWM-EA	WinNT, Lab Windows/CVI DLL and diagnostics	3.5" disk
DKDM-GPNTXFVM-EA	WinNT, LabVIEW4.0 DLL and diagnostics	3.5" disk

*One software package is included with order. Additional software packages are available for \$150.

NC=No Charge (included with hardware)

SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729

BusXchange™ Multiplex Bus Switch

ORDER NUMBER	DESCRIPTION
DHAS-MBS1616	16 LRUs by 16 buses

NOTES:

1. LRU is a "Line Replaceable Unit." Refers to any 1553 device: BC, RT, and/or Monitor.
The device may be real or emulated. Multiplex Bus Switch supports only transformer-coupled devices.
2. Does not include +5V power supply.
3. Resource Allocation Manager™ (RAM) Gold software is included with each BusXchange Switch at no charge.

Resource Allocation Manager™ (RAM) Software for BusXchange™

ORDER NUMBER	DESCRIPTION	MEDIA TYPE
DKDM-MBSRAM00-RA	RAM Gold Software: For managing the selection and interconnection of resources.	CD ROM
DKDM-MBSRGP00-RA	RAM Gold+ Software: Supports multiple simultaneous users via a client-server architecture. Supports server and 5 clients.	CD ROM
DKDM-MBSRGM00-RA	RAM Gold+ MSS: Multiple Switch Server (MSS) for support of an additional six switch devices.	CD ROM

Note: All RAM software runs under Windows NT 4.0 and Windows 2000.

BusXchange™ Multiplex Bus Switch Accessory

ORDER NUMBER	DESCRIPTION
H-AS-PWRSPPLY-10	+5V Power Supply

SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729

REPAIR & MAINTENANCE

Product Repair (Non-Warranty or Out-of-Warranty Products)

Systran recommends executing the confidence test prior to contacting the Systran Customer Support Department. Please have the failure description and serial number of the card available when calling for a Return Material Authorization (RMA) number. Also specify the desired method for processing of the repair.

Hardware Repair

ORDER NUMBER	UNIT DESCRIPTION
O-SR-SPECIAL1	Repair Time by the Hour+ Cost of Parts and Materials (4 Hr. min.)

Annual Hardware Maintenance Agreement (1)

ORDER NUMBER	UNIT DESCRIPTION
DMAS-XXXXXXXX-N (2)	1553 Board Annual Maintenance

Resource Allocation Manager™ (RAM) Software Maintenance

ORDER NUMBER	DESCRIPTION
MKDM-MBSRAM00-RA	Annual Maintenance for RAM Gold
MKDM-MBSRGP00-RA	Annual Maintenance for RAM Gold+
MKDM-MBSRGM00-RA	Annual Maintenance for RAM Gold+ with MSS

Note:

- (1) This agreement covers hardware component failures only.
 (2) The "XXXXXXXX" corresponds to the middle eight characters of the hardware Part Number (e.g. GLD+PC, GLD+VX/C, etc.). The "N" is the number of channels on the board (1 or 2).

TECHNICAL SERVICES**Consulting, Travel, Integration Services and NRE**

ORDER NUMBER	UNIT DESCRIPTION
O-SR-SER0001	Hourly Consulting-Sr. Staff
O-SR-SER0002	Hourly Consulting-Staff
O-SR-SER0003	On-Site Travel & Per Diem
O-SR-SER0004	Professional Services

SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
 Phone (937) 252-5601 FAX (937) 258-2729

**Systran 1553 Solutions
December 1, 2003**

Full View Price List 1

Accessories

Order No.	Name	Description	Length
*DHAS-54-10841	Tee Connector	1553 3-lug Tee Connector (Trompeter BN73 or equivalent)	
*DHAS-42-01179	Terminator Plug	1553 Terminator Plug (Trompeter TNG 1-1-78 or equivalent)	
DHAS-01-01195	Bus Coupler	1553 Transformer Coupler Box with 3-lug Bulkhead Jacks	
DHAS-06-01602-8	Standard 1553 Cable	1553 Bus Cable Assembly with 3-lug Cable Plug Connectors (\$.55/ft. for extra cable)	8 ft.
DHAS-06-01269-3	1553 Interface Cable Set	Allows a dual redundant 1553 bus to be routed to the interface for a very short direct stub connection, then back off the interface for termination or continuation to another device on the bus. It may also be used for transformer stub connection, however two of the four bus cables are left unused.	3 ft.
DHAS-06-11539-5	P2 Connector Cable Assembly	Available for the following products: DHAS-BIU-183V, DHAS-BIU-153V, DHAS-BIU-143V	5 ft.
DHAS-06-11474-1	1120/21 Cable Assembly	Direct Coupled Cable for the DHAS-DTI-1120 and DHAS-DTI-1121	8 in.
DHAS-06-11474-4			4 ft.
DHAS-06-11474-8			8 ft.
DHAS-06-11475	1120/21 Cable Assembly	Transformer Coupled Cable for the DHAS-DTI-1120 and DHAS-DTI-1121	12 in.
DHAS-06-13168-1	212X Cable Assembly	Direct Coupled Cable for the DHAS-DTI-212X and the DHAS-GLD-PC/S-1 with plugs.	8 in.
DHAS-06-13168-4			4 ft.
DHAS-06-13168-8			8 ft.
DHAS-06-13171-1	212X Cable Assembly	Transformer Coupled Cable for the DHAS-DTI-212X and the DHAS-GLD-PC/S-1 with jacks.	8 in.
DHAS-06-13171-4			4 ft.
DHAS-06-13171-8			8 ft.
DHAS-06-13171-18			18 ft.
DHAS-04-11239	MicroVAXII Bulkhead	Cabling kit for MicroVAX II. Includes BIU connector, cable to MicroVAX II bulkhead, and bulkhead adapter.	
DHAS-04-12512	MicroVAX Cabling Kit	MicroVAX 3XXX and VAX4000 bulkhead cable kit (for use with single board products)	
DHAS-21-01126	Connector Cable Assembly	Bulkhead cable assembly for the DHAS-DTI-PC and DHAS-DTI-PC/S, for single and dual channel	4 in.
DHAS-30891-8	Single Channel Cable Assembly	Cable Assembly for DHAS-GLD+PC/S-1 and DHAS-GLD+ PC-1 with plugs.	8 in.
DHAS-30892-8	Dual Channel Cable Assembly	Cable Assembly for DHAS-GLD+PC/S-2 and DHAS-GLD+PC-2 with plugs	8 in.
DHAS-30893-1	Single Channel Cable Assembly	Cable Assembly for DHAS-GLD+PCI/S-1 and DHAS-GLD+PCI-1 with jacks	1 in.
DHAS-WGD+PCI2	Dual Channel Cable Assembly	Cable Assembly for DHAS-GLD+PCI/S-2 and DHAS-GLD+PCI-2 with jacks	2 in.
DHAS-30893-8	Single Channel Cable Assembly	Cable Assembly for DHAS-GLD+PC/S-1 and DHAS-GLD+PC-1 with jacks	8 in.
DHAS-30894-8	Dual Channel Cable Assembly	Cable Assembly for DHAS-GLD+PC/S-2 and DHAS-GLD+PC-2 with jacks	8 in.
DHAS-GLD+PMCAD-6	Cable Assembly	1553 Cable Assembly for GLD+PMC/PCI boards.	6 in.
BHAS-CPCI2PMC-2	CompactCPI Carrier	CompactPCI® Slave 2-Slot PMC Module Carrier Board Inv. Acct. No. 1159-003-00	N/A
(See manual)	(See manual)	Extra copy of manual.	N/A

*Sales Acct. No.: 7470-001-30 Inventory Acct. No.: 1159-004-00

**SYSTRAN Corp., 4126 Linden Avenue, Dayton, OH 45432-3068 USA
Phone (937) 252-5601 FAX (937) 258-2729**



Artisan Technology Group is your source for quality new and certified-used/pre-owned equipment

- FAST SHIPPING AND DELIVERY
- TENS OF THOUSANDS OF IN-STOCK ITEMS
- EQUIPMENT DEMOS
- HUNDREDS OF MANUFACTURERS SUPPORTED
- LEASING/MONTHLY RENTALS
- ITAR CERTIFIED SECURE ASSET SOLUTIONS

SERVICE CENTER REPAIRS

Experienced engineers and technicians on staff at our full-service, in-house repair center

*InstraView*SM REMOTE INSPECTION

Remotely inspect equipment before purchasing with our interactive website at www.instraview.com ↗

WE BUY USED EQUIPMENT

Sell your excess, underutilized, and idle used equipment. We also offer credit for buy-backs and trade-ins. www.artisanng.com/WeBuyEquipment ↗

LOOKING FOR MORE INFORMATION?

Visit us on the web at www.artisanng.com ↗ for more information on price quotations, drivers, technical specifications, manuals, and documentation

Contact us: (888) 88-SOURCE | sales@artisanng.com | www.artisanng.com